SUPPLY TABLE

	UNIT: Petajoule (10 ¹⁵)	Agriculture and forestry	Mining	Electricity supply	Other industries	Households	Inventories	Imports	Environment	Total
Natural inputs	Extraction of coal								200	200
	Electricity from solar panels and wind mills								36	36
	Wood								20	20
Products	Coal		198	3						198
	Gasoline							40		40
	Electricity			156						156
	Fuel wood	20								20
Residuals	Losses during extraction (coal)		2	2						2
	Losses during distribution (electricity)			9						9
	Losses during transformation			66						66
	Other losses (due to end use)									
	gasoline	15	3	3 1	14	12				45
	electricity	4	5	5	77	24				110
	fuel wood					20				20
Total supply of energy		39	208	3 232	91	56	0	40	256	922

USE TABLE

	UNIT: Petajoule (1015)	Agriculture and forestry	Mining	Electricity supply	Other industries	Households	Inventories	Exports	Environment	Total
Natural inputs	Extraction of coal		200							200
	Electricity form solar panels and wind mills			36						36
	Wood	20								20
Products	Coal			195			3			198
	Gasoline	15	3	1	14	12	-5			40
	Electricity	4	5		77	24		46		156
	Fuel wood					20				20
Residuals	Losses during extraction (coal)								2	2
	Losses during distribution (electricity)								9	9
	Losses during transformation								66	66
	Other losses (due to end use)									
	gasoline								45	45
	electricity								110	110
	fuel wood								20	20
Total use of energy		39	208	232	91	56	-2	46	252	922